





17


- N x4
- R 5mm x8
- JA 3x13 x4



18








- WC x4
- YA x6
- J 3,5x16 x12







- | | | | | | | | |
|---------------|--------|----------|-------------|--------------|---------------|--------------|-------------|
| IA x1 | N x4 | R 5mm x8 | C 15x10 x40 | B 34mm x32 | BA x8 | A 8x35 x38 | FB 7x50 x14 |
| WA 4mm x1 | Z x6 | YA x6 | JA 3x13 x4 | J 3,5x16 x12 | JB 2,5x16 x48 | JI 3,5x40 x6 | T x2 |
| JD 4,5x40 x12 | IB x20 | WC x4 | | | | | |

2









4




11



5



12



6

